



# Release Notes for Cisco DX Series Firmware Release 10.2(5)ES

---

First Published: 2016-12-22

## Release Notes for Cisco DX Series Firmware Release 10.2(5)ES

### New and Changed Features

There are no new or changed features for this release.

### Resolved Caveats

The following table shows caveats that were resolved in this release.

<a href="#">CSCvc44073</a>	Display on DX80 flickers
----------------------------	--------------------------

### Installation Notes

#### System Requirements

Cisco DX Series devices are supported by Cisco Unified Communications Manager Release 8.5(1), 8.6(1), 8.6(2), 9.1(2), 10.5(1) and later.

The initial release of Cisco DX Series devices requires the latest device pack installed on each Cisco Unified Communications Manager release.

#### Cisco Unified Communication Manager Public Keys

To improve software integrity protection, new public keys are used to sign cop files for Cisco Unified Communications Manager Release 10.0.1 and later. These cop files have “k3” in their name. To install a k3 cop file on a pre-10.0.1 Cisco Unified Communications Manager, consult the README for the `cisco.cm.version3-keys.cop.sgn` to determine if this additional cop file must first be installed on your specific Cisco Unified Communications Manager version. If these keys are not present and are required, you will see the error “The selected file is not valid” when you try to install the software package.

## Install Firmware Release on Cisco Unified Communications Manager

Before using the Cisco DX Series firmware release on the Cisco Unified Communications Manager, install the latest Cisco Unified Communications Manager firmware on all Cisco Unified Communications Manager servers in the cluster.

- 
- Step 1** Go to the following URL: <http://software.cisco.com/download/navigator.html>.
- Step 2** Choose **Collaboration Endpoints** > **Collaboration Desk Endpoints** > **Cisco DX Series**.
- Step 3** Choose your device type.
- Step 4** In the Latest Releases folder, choose **10.2(5.215)**.
- Step 5** Select one of the following firmware files, click the **Download** or **Add to cart** button, and follow the prompts:
- For Cisco DX70: cmterm-dx70.10-2-5-215.k3.cop.sgn
  - For Cisco DX80: cmterm-dx80.10-2-5-215.k3.cop.sgn
  - For Cisco DX650: cmterm-dx650.10-2-5-215.k3.cop.sgn
  - For all Cisco DX Series devices: cmterm-dxseries.10-2-5-215.k3.cop.sgn

**Note** If you added the firmware file to the cart, click the **Download Cart** link when you are ready to download the file.

- Step 6** Click the arrow next to the firmware filename in the Download Cart section to access additional information about this file. The link for the readme file is in the Additional Information section. The readme file contains installation instructions for the corresponding firmware.
- Step 7** Follow the instructions in the readme file to install the firmware.
- 

## Install Firmware ZIP files

If a Cisco Unified Communications Manager is not available to load the installer program, the following .zip files are available to load the firmware.

Firmware upgrades over the WLAN interface may take longer than upgrades that use a wired connection. Upgrade times over the WLAN interface may take more than an hour, depending on the quality and bandwidth of the wireless connection.

- 
- Step 1** Go to the following URL: <http://software.cisco.com/download/navigator.html>.
- Step 2** Choose **Collaboration Endpoints** > **Collaboration Desk Endpoints** > **Cisco DX Series**.
- Step 3** Choose your device type.
- Step 4** In the Latest Releases folder, choose **10.2(5.215)**.
- Step 5** Download the relevant zip files.
- For Cisco DX70: cmterm-dx70.10-2-5-215.zip
  - For Cisco DX80: cmterm-dx80.10-2-5-215.zip

- For Cisco DX650: cmterm-dx650.10-2-5-215.zip

**Step 6** Unzip the files.

**Step 7** Manually copy the unzipped files to the folder on the TFTP server. See *Cisco Unified Communications Operating System Administration Guide* for information about how to manually copy the firmware files to the server.

---

## Important Note

### Cisco Virtual Office Setup

In a Cisco Virtual Office setup, Cisco recommends the use of a Cisco 881 Integrated Services Router instead of the Cisco 871 router.

## Limitations and Restrictions

- When a user is sharing their computer desktop in a Cisco DX70 or a Cisco DX80 presentation call, any audio from the desktop is not shared.
- Users should only pair their mobile phone with one Cisco DX Series device at a time.
- The only supported external cameras for Cisco DX650 are the Logitech C920-C Webcam and Logitech C930e.
- Cisco DX Series devices do not support Android apps that require portrait mode, GPS, or Accelerometer. However, apps that support both portrait and landscape are supported in landscape mode.
- Use the Google Play™ Store to find and add applications to your devices. Depending on your security settings, the Google Play Store may not be available. Cisco does not guarantee that an application that you download from a third-party site works.
- For Cisco DX70, the HDMI Out port only supports mirror mode.

For Cisco DX80, the HDMI Out port is disabled.

Cisco DX650 and Cisco DX70 support HDCP through the HDMI Out port in mirror mode. An HDMI monitor (or any HDMI sink device) that is connected to a Cisco DX650 or a Cisco DX70 must be HDCP-compliant. Cisco DX Series devices do not support HDCP on the HDMI in port.

- Cisco DX650 devices labeled with TAN 68-5217-xx can't be downgraded below version 10.2(2).
- Cisco DX70 and Cisco DX80 No Radio (NR) hardware models can't be downgraded below version 10.2(4.99).
- Cisco DX70 devices labeled with TAN 68-5387-06 can't be downgraded below version 10.2(5).
- Cisco DX80 devices labeled with TAN 68-5673-01 can't be downgraded below version 10.2(5).
- After a firmware upgrade, a device that was previously deployed with a static IP address may default back to DHCP.

## Workarounds for Known Issues

- If you are deploying Cisco DX Series devices for secure calls with IPv6 and an earlier Cisco Unified Communications Manager version than Release 11, go to the CUCM **Service Parameters** page, select **Advanced Options**, and set **SIP Max Incoming Message Size** to the maximum setting (20000).
- There is a known issue when using a Jabra 450 handset, with audio occasionally coming out of the DX device speaker instead of the handset. the workaround is to unplug the USB cable from the handset base, then plug it back in.
- Due to a known issue (CSCux21956), users that are creating a new contact with a Japanese language name should only leave a single space between last and first names. If more than one space is included between the names, that contact will not show up in search results when the user searches by first name.
- There is a known issue with Cisco DX650 speakerphone calls. If one side's audio level is higher than the other side's, then the other side's audio will be attenuated. This means that it is possible the speakers might not be able to hear each other, or that the volume of the far end will be reduced significantly. Adjusting the volume to 70% or less may help to improve this situation, but at higher volume levels this is expected behavior. If adjusting the volume does not improve the situation, we recommend using the handset or a headset for your calls instead.

## Device Redistribution

When an administrator redistributes a device (that is, gives the device to a different user), the administrator should execute a factory reset of the device to remove any user data that was previously stored on the device.

If an administrator changes the user ID of a device from user A to user B, none of the data that is associated with user A will be available to user B. The new user must download apps and other data. This scenario may apply to a single user that changes from an old user ID to a new user ID.

## Behavior During Times of Network Congestion

Anything that degrades network performance can affect voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

To reduce or eliminate any adverse effects, schedule administrative network tasks during a time when the devices are not being used or exclude the devices from testing.

## Supported Languages

Arabic, Egypt ( ar_EG )	French, France ( fr_FR )	Portuguese, Brazil ( pt_BR )
Bulgarian, Bulgaria ( bg_BG )	German, Germany ( de_DE )	Portuguese, Portugal ( pt_PT )
Catalan, Spain ( ca_ES )	Greek, Greece ( el_GR )	Romanian, Romania ( ro_RO )
Chinese, PRC ( zh_CN )	Hebrew, Israel ( he_IL )	Russian ( ru_RU )

Chinese, Taiwan ( zh_TW )	Hungarian, Hungary ( hu_HU )	Serbian, Republic of Serbia ( sr_RS )
Croatian, Croatia ( hr_HR )	Italian, Italy ( it_IT )	Slovak, Slovakia ( sk_SK )
Czech, Czech Republic ( cs_CZ )	Japanese ( ja_JP )	Slovenian, Slovenia ( sl_SI )
Danish, Denmark ( da_DK )	Korean ( ko_KR )	Spanish, Spain ( es_ES )
Dutch, Netherlands ( nl_NL )	Latvian, Latvia ( lv_LV )	Swedish, Sweden ( sv_SE )
English, Britain ( en_GB )	Lithuanian, Lithuania ( lt_LT )	Thai, Thailand ( th_TH )
English, US ( en_US )	Norwegian bokmål , Norway ( nb_NO )	Turkish, Turkey ( tr_TR )
Finnish, Finland ( fi_FI )	Polish ( pl_PL )	

## Documentation, Service Requests, and Additional Information

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.

## Related Documentation

### Cisco DX Series

All Cisco DX Series documentation is available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/tsd-products-support-series-home.html>

User-oriented documents are available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/products-user-guide-list.html>

Administrator-oriented documentation is available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/products-maintenance-guides-list.html>

The *Cisco DX Series Wireless LAN Deployment Guide* is available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/products-implementation-design-guides-list.html>

Translated publications are available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/tsd-products-support-translated-end-user-guides-list.html>

Open Source license information is available as the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/products-licensing-information-listing.html>

Regulatory Compliance and Safety Information is available at the following URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/desktop-collaboration-experience-dx600-series/products-installation-guides-list.html>

### **Cisco Unified Communications Manager**

See the *Cisco Unified Communications Manager Documentation Guide* and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following documentation URL:

<http://www.cisco.com/c/en/us/support/unified-communications/unified-communications-manager-callmanager/tsd-products-support-series-home.html>

### **Cisco Business Edition 6000**

Refer to the *Cisco Business Edition 6000 Documentation Guide* and other publications that are specific to your Cisco Business Edition 6000 release. Navigate from the following URL:

<http://www.cisco.com/c/en/us/support/unified-communications/business-edition-6000/tsd-products-support-series-home.html>

### **Cisco and the Environment**

Related publications are available at the following URL:

<http://www.cisco.com/go/ptrdocs>

---

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <http://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2016 Cisco Systems, Inc. All rights reserved.