SUPPORT DOCUMENT

Installing Lync Certificate on Polycom CX8000

This document describes how you can manually install Lync certificate on Polycom CX8000 (Crestron RL) codec.

Step 1.
Please make sure that a USB thumb drive with Lync certificate is connected to the CX8000 codec.

Step 2.
Tap [Options] menu from the table console and tap [Settings].



Step 3.
Enter CX8000 Administrator's credential. The system will restart after authentication.

Step 4.
Type the Administrator's password again when the system boots up.



Step 5.
Tap [OEM Setting] from the left navigation menu and tap [Security].





Step 6.
Tap [Import] and select Lync certificate from USB thumb drive that is connected to the codec. After import is successfully executed, exit from the settings mode (the system will reboot and goes back to the normal mode).