Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- Firmware Version：

  T46G: 28.71.0.176 Upgrade to 28.71.0.224

  T42G: 29.71.0.53 Upgrade to 29.71.0.224

  T41G: 36.71.0.112 Upgrade to 36.71.0.224
- Applicable Models: SIP-T46G/T42G/T41G
- Release Date: June 19, 2014

2. New Features

3. Optimization

4. Bug Fixes

1. Fixed the issue that the T4 series displayed a wrong call ID when using directed call pickup of a monitored BLF line.
2. Fixed the issue that the BLF doesn't work under 3CX SBC environment.